



# MERCEDES-BENZ COLLISION RICHMOND

#105-11100 CAMBIE ROAD  
RICHMOND, BC V6X 1K9

Mercedes-Benz

P: 604-248-1720

F: 604-248-1721

03/13/2020

INVOICE

PRIV75127

A & A CONTRACT CUSTOMER BROKERS LTD

BLACK 08 MAYBACH 62

License Plate : JK062S Mileage : 104560

V.I.N. : WDBVG79JX8A002414

Estimate # : 54146 Created On : 03/06/2020

Estimator : ALLAN FUNG

PRIVATE

Claim # : PRIVATE

PO # :

Unit # :

Regie # : \*

PST # :

Opened On : 03/06/2020

Delivered On : 03/13/2020

Closed On : 03/13/2020

## REPAIR DESCRIPTION

Starter Battery 001 982 82 08 26 0.0 460.00

## FINAL REPAIR COST CALCULATIONS:

Body	0.0 @	73.41	0.00	Parts	460.00	Ded.	0.00	
Alum / Diag	0.0 @	0.00	0.00	Sublet	0.00	Dep.	0.00	
Electrical	0.0 @		0.00	Towing				
Refinish	0.0 @	73.41	0.00	PVRT		G/HST Pay		
Structural	0.0 @	73.41	0.00	Levies		Other		
Frame	0.0 @	83.90	0.00	<b>Insured's portion total</b>				<b>0.00</b>
Mechanical	0.0 @	94.39	0.00	Mechanical preset operations included in "Mechanical" total				0.00
Glass	0.0 @	73.41	0.00	Adjustment				0.00
DETAIL	0.0 @	0.00	0.00	<b>SUBTOTAL</b>				<b>460.00</b>
ENVIRO	0.0 @	0.00	0.00	R816773147 G/HST				23.00
PDR	0.0 @	0.00	0.00	1002-0047 PST				32.20
USER3	0.0 @		0.00	<b>TOTAL PAYABLE</b>				<b>515.20</b>
USER4	0.0 @	0.00	0.00	Less Insured's Portion				0.00
ATP	0.0 @		0.00	<b>NET REPAIRS</b>				<b>515.20</b>
Paint mat.	0.0 @	0.00	0.00					
Shop mat.	0.0 @	0.00	0.00					

I, the registered owner or representative of the above described vehicle authorize the repairs and also any additional private repairs that are on the attached repair estimate or as verbally authorized by myself including all necessary parts sublet and materials. I do understand that my vehicle and contents are left strictly at my own risk. I am aware to the above repairs.  
Date: \_\_\_\_\_

I, \_\_\_\_\_ the registered owner, or representative, of the above described vehicle state the above vehicle appears to have been repaired satisfactorily. I HEREBY ACKNOWLEDGE MY INDEBTNESS IN THE AMOUNT OF \$ \_\_\_\_\_ BEING THE TOTAL AMOUNT OWING OR BALANCE OWING AS SHOWN. Date: \_\_\_\_\_

## GUARANTEE

NO.1 COLLISION GROUP GUARANTEES THAT ALL REPAIRS PERFORMED UNDER REPAIR ORDER HAVE BEEN COMPLETED TO GENERALLY ACCEPTED INDUSTRY STANDARDS. THIS GUARANTEE PROTECTS AGAINST DEFECTIVE WORKMANSHIP OR MATERIALS. PROVIDING THE DESCRIBED VEHICLE REMAINS OWNED AND REGISTERED TO THE INDIVIDUAL NAMED ABOVE, THIS GUARANTEE IS VALID FROM THE DATE OF ISSUE FOR THE LIFE OF VEHICLE ON BODY AND PAINT REPAIRS; AND FOR SUCH A PERIOD OF TIME AS SPECIFIED BY THE PARTS SUPPLIER.

NO.1 COLLISION GROUP PROVIDES A LIFETIME WARRANTY, FROM EFFECTIVE DATE STATED ON WARRANTY, ON PAINTING-RELATED PRIMING AND PAINTING WORK AGAINST SOLVENT BLISTERING, PEELINGS, OR HAZING THAT WOULD BE A DIRECT RESULT OF OUR WORKMANSHIP AND OR THE QUALITY OF THE PAINT. SPECIFICALLY EXCLUDED ARE INCIDENTAL COSTS, SUCH AS TOWING FEES, CAR RENTAL CHARGES, TRAVEL EXPENSES, OR ASSEMBLIES AND COMPONENTS WHICH ARE NOT SPECIFICALLY COVERED BY WRITTEN WARRANTY. WARRANTY WILL EXCLUDE NORMAL WEAR AND TEAR, ROCK CHIPS, RUST, NEW DAMAGE, OR DAMAGE RESULTING FROM UNREASONABLE USE, MAINTENANCE OR CARE OF THE VEHICLE. ALL WARRANTY AGREEMENTS ARE NON-TRANSFERABLE.

CUSTOMER #: 130817

62515



Mercedes-Benz of Bellingham

\*INVOICE\*

1100 IOWA ST. BELLINGHAM, WA 9822 Phone: (360) 676-0600

GRAHAM ROBINS 421 E LAKE SAMISH DR BELLINGHAM, WA 98229

PAGE 1

HOME: CONT:850-405-5344 BUS: CELL:850-405-5344

SERVICE ADVISOR: 317 RYAN LAMBERT

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG, DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE

R.O. OPENED READY OPTIONS: DLR:84143

13:33 18AUG25 15:10 13OCT25

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Includes service items like TOZPCSV2 and 1HW HAZARDOUS WASTE DISPOSAL FEE.

PARTS: 158.42 LABOR: 111.03 OTHER: 9.51 TOTAL LINE A: 278.96

B CUSTOMER STATES VEHICLE IS HAVING ISSUES WITH FRONT PORTION OF VEHICLE ELECTRONICS. CUSTOMER STATES THAT MULTIPLE ITEMS ARE NOT WORKING AND THAT CONSUMER PROTECTION MODE IS ACTIVE. ITEMS INCLUDE WINDOWS, REAR AC, REAR SEATING ADJUSTMENT. PLEASE DIAGNOSE AND ADVISE

CAUSE: 12V BATTERY

51TOZZ2 CUSTOMER STATES VEHICLE IS HAVING ISSUES WITH FRONT PORTION OF VEHICLE ELECTRONICS. CUSTOMER STATES THAT MULTIPLE ITEMS ARE NOT WORKING AND THAT CONSUMER PROTECTION MODE IS ACTIVE. ITEMS INCLUDE WINDOWS, REAR AC, REAR SEATING ADJUSTMENT. PLEASE DIAGNOSE AND ADVISE

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Includes items like 1 001-982-82-08 STARTER BATTERY H8A 95 AH.

PARTS: 447.56 LABOR: 328.50 OTHER: 0.00 TOTAL LINE B: 776.06

65998 12V BATTERY HOOKED UP BATTERY MAINTAINER AND XENTRY DIAGNOSIS. RAN A SHORT TEST AND FOUND A LARGE QUANTITY OF CODES PRESENT FOR UNDERVOLTAGE AND WHEN CHARGER IS DISCONNECTED, BATTERY DROPS TO 4 VOLTS. RECOMMEND REPLACING THE 12V BATTERY TO START AND SEE WHAT PROBLEMS REMAIN PRESENT WITH NEW BATTERY INSTALLED.

\*\*\*\*\*

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE...

\*SHOP SUPPLY COSTS: We have added a charge equal to 12% of the total cost of labor and parts, not to exceed \$100, to the Repair Order for shop supplies used in connection with this repair.

Table with columns: DESCRIPTION, TOTALS. Includes rows for LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES \*, TOTAL CHARGES, LESS INSURANCE, SALES TAX, PLEASE PAY THIS AMOUNT.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 130817

62515



Mercedes-Benz of Bellingham

\*INVOICE\*

1100 IOWA ST. BELLINGHAM, WA 9822 Phone: (360) 676-0600

GRAHAM ROBINS 421 E LAKE SAMISH DR BELLINGHAM, WA 98229

PAGE 2

HOME: CONT:850-405-5344 BUS: CELL:850-405-5344

SERVICE ADVISOR: 317 RYAN LAMBERT

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG, DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE

Table with columns: R.O. OPENED, READY, OPTIONS, DLR:84143

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL

C CUSTOMER REQUESTS TO PERFORM PRE-PURCHASE INSPECTION 80TOZPPI CUSTOMER REQUESTS TO PERFORM PRE-PURCHASE INSPECTION

D CUSTOMER REQUESTS VISUAL INSPECTION OF VEHICLE 00TOZMPINSPECT CUSTOMER REQUESTS VISUAL INSPECTION OF VEHICLE

E\*\* ENGINE AIR FILTER CAUSE: ENGINE AIR FILTERS REP ENGINE AIR FILTER

F\*\* BRAKE FLUSH SBC CAUSE: BRAKE FLUSH REP BRAKE FLUSH SBC

G\*\* SPARK PLUGS CAUSE: SPARK PLUGS REP SPARK PLUGS

Table with columns: WARRANTY DISCLAIMER, SHOP SUPPLY COSTS, DESCRIPTION, TOTALS

CUSTOMER #: 130817

62515



Mercedes-Benz of Bellingham

\*INVOICE\*

GRAHAM ROBINS
421 E LAKE SAMISH DR
BELLINGHAM, WA 98229

1100 IOWA ST.
BELLINGHAM, WA 9822
Phone: (360) 676-0600

PAGE 3

HOME: CONT:850-405-5344
BUS: CELL:850-405-5344

SERVICE ADVISOR: 317 RYAN LAMBERT

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG. Values: 08, MERCEDES-BENZ MAYBAC, WDBVG79JX8A002414, 65998/66014, T8671.

Table with columns: DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Values: 01JAN08 DD, 17:00 13OCT25, 245.70, VISA, 13OCT25.

Table with columns: R.O. OPENED, READY, OPTIONS. Values: 13:33 18AUG25, 15:10 13OCT25, DLR:84143.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Includes parts list for spark plugs and fuel filter.

Table with columns: PARTS, LABOR, OTHER, TOTAL LINE. Includes parts list for fuel filter replacement.

Table with columns: I\*\*, REPLACE CABIN AIR FILTER, CAUSE, REP REPLACE CABIN AIR FILTER. Includes parts list for cabin air filter.

Table with columns: PARTS, LABOR, OTHER, TOTAL LINE. Includes parts list for cabin air filter replacement.

Table with columns: J\*\*, TRANSMISSION SERVICE, CAUSE, REP TRANSMISSION SERVICE. Includes parts list for transmission service.

Table with columns: PARTS, LABOR, OTHER, TOTAL LINE. Includes parts list for transmission service.

Table with columns: PARTS, LABOR, OTHER, TOTAL LINE. Includes parts list for transmission service.

Complex table containing WARRANTY DISCLAIMER, SHOP SUPPLY COSTS, and signature lines for customer and dealership.

CUSTOMER #: 130817

62515



Mercedes-Benz of Bellingham

\*INVOICE\*

1100 IOWA ST. BELLINGHAM, WA 9822 Phone: (360) 676-0600

GRAHAM ROBINS 421 E LAKE SAMISH DR BELLINGHAM, WA 98229

PAGE 4

HOME: CONT:850-405-5344 BUS: CELL:850-405-5344

SERVICE ADVISOR: 317 RYAN LAMBERT

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG. Values: 08, MERCEDES-BENZ MAYBAC, WDBVG79JX8A002414, 65998/66014, T8671

Table with columns: DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Values: 01JAN08 DD, 17:00 13OCT25, 245.70, VISA, 13OCT25

Table with columns: R.O. OPENED, READY, OPTIONS: DLR:84143

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Includes description: K\*\* RIGHT MIRROR ADJUSTMENT NOT WORKING

CAUSE: RIGHT MIRROR DRIVE MOTOR REP DIAGNOSE RIGHT MIRROR ADJUSTMENT 3134 C 1.00 219.00 219.00

PARTS: 213.35 LABOR: 219.00 OTHER: 0.00 TOTAL LINE K: 432.35 65998 RIGHT MIRROR DRIVE MOTOR ATTEMPTED ACTUATING COMPONENT

L\*\* REAR WINDOW SHADES DO NOT CLOSE CAUSE: RELAYS REP DIAGNOSE REAR WINDOW SHADES 3134 C 1.00 219.00 219.00

PARTS: 29.10 LABOR: 219.00 OTHER: 0.00 TOTAL LINE L: 248.10 65998 RELAYS HOOKED UP BATTERY MAINTAINER AND XENTRY DIAGNOSIS

M\*\* LEFT REAR SEAT FOOT REST ADJUSTMENT NOT WORKING PROPERLY CAUSE: NORMALIZATION REP DIAGNOSE LEFT REAR SEAT 3134 C 1.00 219.00 219.00

Table with columns: WARRANTY DISCLAIMER, SHOP SUPPLY COSTS, DESCRIPTION, TOTALS. Includes items: LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES, TOTAL CHARGES, LESS INSURANCE, SALES TAX

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

CUSTOMER #: 130817

62515



Mercedes-Benz of Bellingham

\*INVOICE\*

GRAHAM ROBINS
421 E LAKE SAMISH DR
BELLINGHAM, WA 98229

1100 IOWA ST.
BELLINGHAM, WA 9822
Phone: (360) 676-0600

PAGE 5

HOME: CONT:850-405-5344
BUS: CELL:850-405-5344

SERVICE ADVISOR: 317 RYAN LAMBERT

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG. Values: 08, MERCEDES-BENZ MAYBAC, WDBVG79JX8A002414, 65998/66014, T8671.

Table with columns: DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Values: 01JAN08 DD, 17:00 13OCT25, 245.70, VISA, 13OCT25.

Table with columns: R.O. OPENED, READY, OPTIONS. Values: 13:33 18AUG25, 15:10 13OCT25, DLR:84143.

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

N\*\* WASHER FLUID LEAKING. CANNOT IDENTIFY WHERE LEAK IS COMING FROM.
CAUSE: WASHER FLUID RESERVOIR
REP DIAGNOSE WASHER FLUID LEAKING
3134 C 1.00 219.00 219.00
1 140-333-03-74 SCREW 32.01 32.01 32.01
1 220-540-00-45 SWITCH 32.01 32.01 32.01
1 220-997-19-81-64 GROMMET 11.28 11.28 11.28
PARTS: 75.30 LABOR: 219.00 OTHER: 0.00 TOTAL LINE N: 294.30
65998 WASHER FLUID RESERVOIR LIFTED VEHICLE AND INSPECTED RESERVOIR FROM ALL SIDES. FOUND NO LEAK COMING FROM AND OF THE SEALS ON THE TANK. TANK HAS A LEAK IN IT. RECOMMEND REPLACING WASHER FLUID RESERVOIR

O\*\* VALVE COVER GASKETS LEAKING
CAUSE: VALVE COVER GASKETS
REP VALVE COVER GASKETS LEAKING
3134 C 6.00 1314.00 1314.00
1 137-016-03-21 GASKET 57.61 57.61 57.61
1 137-016-02-21 GASKET 55.50 55.50 55.50
PARTS: 113.11 LABOR: 1314.00 OTHER: 0.00 TOTAL LINE O: 1427.11
65998 VALVE COVER GASKETS REMOVED VALVE COVERS AND CLEANED. REPLACED GASKETS AND REINSTALLED. TEST DROVE AND FOUND COVERS ARE NO LONGER LEAKING.

P\*\* PERFORM MERCEDES-BENZ WHEEL ALIGNMENT
CAUSE: ALIGNMENT
05TOZCVSUS1 PERFORM MERCEDES-BENZ WHEEL ALIGNMENT
3134 C 2.00 199.99 199.99
PARTS: 0.00 LABOR: 199.99 OTHER: 0.00 TOTAL LINE P: 199.99
65998 ALIGNMENT PERFORMED ALIGNMENT

Q\*\* RIGHT MIRROR DRIVE MOTOR
CAUSE: MIRROR MOTOR
REP RIGHT MIRROR DRIVE MOTOR
3134 C 1.00 219.00 219.00

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE...

Table with columns: \*SHOP SUPPLY COSTS: DESCRIPTION, TOTALS. Rows include LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES \*, TOTAL CHARGES, LESS INSURANCE, SALES TAX.

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE PLEASE PAY THIS AMOUNT

CUSTOMER #: 130817

62515



Mercedes-Benz of Bellingham

\*INVOICE\*

GRAHAM ROBINS
421 E LAKE SAMISH DR
BELLINGHAM, WA 98229

1100 IOWA ST.
BELLINGHAM, WA 9822
Phone: (360) 676-0600

PAGE 6

HOME: CONT:850-405-5344
BUS: CELL:850-405-5344

SERVICE ADVISOR: 317 RYAN LAMBERT

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG, DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE

R.O. OPENED READY OPTIONS: DLR:84143

13:33 18AUG25 15:10 13OCT25

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL

PARTS: 213.35 LABOR: 219.00 OTHER: 0.00 TOTAL LINE Q: 432.35

65998 MIRROR MOTOR REMOVED OLD MOTOR AND INSTALLED NEW ONE.
FUNCTION TESTED AND FOUND MIRROR NOW MOVES PROPERLY AS DESIGNED.

\*\*\*\*\*

R\*\* WASHER FLUID RESERVOIR
CAUSE: WASHER RESERVOIR LEAKING
REP WASHER FLUID RESERVOIR

Table with columns: PARTS, LABOR, OTHER, TOTAL LINE R

PARTS: 107.11 LABOR: 1095.00 OTHER: 0.00 TOTAL LINE R: 1202.11

65998 WASHER RESERVOIR LEAKING REMOVED FRONT BUMPER AND LEFT FRONT
FENDER LINER. REMOVED WASHER FLUID RESERVOIR. SWAPPED COMPONENTS FROM
OLD RESERVOIR TO NEW AND INSTALLED NEW RESERVOIR. REINSTALLED FENDER
LINER AND BUMPER. FILLED RESERVOIR AND FOUND NO LONGER LEAKING. NO
FURTHER CONCERN.

\*\*\*\*\*

S\*\* CUSTOMER REQUESTS MINI DETAIL DETAIL INCLUDES: EXTERIOR WASH,
INTERIOR VACUUM, CLEAN DOOR JAMBS, CLEAN WHEELS, DRESS TIRES
(TIRE SHINE), CLEAN INTERIOR GLASS
90TOZMINI CUSTOMER REQUESTS MINI DETAIL DETAIL
INCLUDES: EXTERIOR WASH, INTERIOR VACUUM,
CLEAN DOOR JAMBS, CLEAN WHEELS, DRESS TIRES
(TIRE SHINE), CLEAN INTERIOR GLASS

7108 ISP 0.80 (N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE S: 0.00

\*\*\*\*\*

CUSTOMER PAY FOR REPAIR ORDER

W.S.T 973.23

Table with columns: WARRANTY DISCLAIMER, SHOP SUPPLY COSTS, DESCRIPTION, TOTALS

CUSTOMER #: 130817

62515

PRE-WORKORDER



Mercedes-Benz of Bellingham

GRAHAM ROBINS
421 E LAKE SAMISH DR
BELLINGHAM, WA 98229
GSROBINS@GMAIL.COM

Page 1 of 2

1100 IOWA ST.
BELLINGHAM, WA 9822
Phone: (360) 676-0600

HOME: CONT: (850) 405-5344

BUS: CELL: (850) 405-5344

SERVICE ADVISOR: Ryan Lambert

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/OUT, TAG, DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE, R.O. OPENED, READY, OPTIONS.

Table with columns: LINE, OP CODE, DESCRIPTION, DURATION, ESTIMATE. Contains items # A through # J with descriptions of services and their estimated costs.

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE...

PARTS: All parts installed are new unless otherwise indicated. Remanufactured and refurbished parts that meet manufacturer approved source part requirements may be installed at our discretion. Additional information is available upon request.

Discard Replaced Parts (INITIAL) Save Replaced Parts (INITIAL)
STORAGE CHARGES I understand that a storage charge equal to \$50 will be assessed and shall accrue daily if I fail to pick up the vehicle within 5 days from the date I am notified that the repairs are complete or after the communication of an estimate if I fail to authorize repairs.

PAYMENT TERMS: I agree to pay for the inspection and repairs I authorize, along with the necessary materials, in Cash or approved credit card upon completion of the repairs unless the Dealership agrees to other payment arrangements in advance.

PRELIMINARY ESTIMATE \$ 11861.06
ESTIMATE: YOU ARE ENTITLED TO A WRITTEN PRICE ESTIMATE FOR THE REPAIRS YOU HAVE AUTHORIZED. YOU ARE ALSO ENTITLED TO REQUIRE THE REPAIR FACILITY TO OBTAIN YOUR ORAL OR WRITTEN AUTHORIZATION TO EXCEED THE WRITTEN PRICE ESTIMATE. YOUR SIGNATURE OR INITIALS WILL INDICATE YOUR SELECTION.

By Signing Below: I agree that: (1) I have read this Repair Order and I authorize the completion of the services/repairs listed above in accordance with the terms and conditions herein; (2) the Dealership is not responsible for any delays caused by the unavailability of parts or shipping by the parts manufacturer, supplier, or transporter or for any loss or damage to the vehicle or articles left in the vehicle in case of fire, theft, hail, wind or any other cause beyond its control;

1. I request an estimate in writing before you begin repairs. Contact me if the price will exceed the estimate by more than ten percent.
2. Proceed with repairs but contact me if the price will exceed \$
3. I do not want a written estimate.

Customer X Date

Table with columns: Original Estimate (Parts & Labor), Estimate Additional Parts & Labor Costs, Additional Repairs Approved By / Telephone #, Name or ID # of Employee Obtaining Authorization, Date & Time.

CUSTOMER #: 130817

62515

PRE-WORKORDER



Mercedes-Benz of Bellingham

GRAHAM ROBINS
421 E LAKE SAMISH DR
BELLINGHAM, WA 98229
GSROBINS@GMAIL.COM

Page 2 of 2

1100 IOWA ST.
BELLINGHAM, WA 9822
Phone: (360) 676-0600

HOME: CONT: (850) 405-5344

BUS: CELL: (850) 405-5344

SERVICE ADVISOR: Ryan Lambert

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/ OUT, TAG, DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE, R.O. OPENED, READY, OPTIONS.

Main repair estimate table with columns: LINE, OP CODE, DESCRIPTION, DURATION, ESTIMATE. Includes line items K through S and a subtotal.

Printed On 10/13/2025 3:14 PM

Sales Tax 979.35

Estimate Expires on 11/12/2025

Total 11861.06

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED...

SHOP SUPPLY COSTS: A charge equal to 5% of the total cost of parts and labor, not to exceed \$50, will be added to the Repair Order for shop supplies used in connection with the repair.

PAYMENT TERMS: I agree to pay for the inspection and repairs I authorize, along with the necessary materials, in Cash or approved credit card upon completion of the repairs unless the Dealership agrees to other payment arrangements in advance...

By Signing Below: I agree that: (1) I have read this Repair Order and I authorize the completion of the services/repairs listed above in accordance with the terms and conditions herein...

Customer X \_\_\_\_\_ Date \_\_\_\_\_

PARTS: All parts installed are new unless otherwise indicated. Remanufactured and refurbished parts that meet manufacturer approved source part requirements may be installed at our discretion.

STORAGE CHARGES I understand that a storage charge equal to \$50 will be assessed and shall accrue daily if I fail to pick up the vehicle within 5 days from the date I am notified that the repairs are complete...

PRELIMINARY ESTIMATE \$ \_\_\_\_\_

ESTIMATE: YOU ARE ENTITLED TO A WRITTEN PRICE ESTIMATE FOR THE REPAIRS YOU HAVE AUTHORIZED. YOU ARE ALSO ENTITLED TO REQUIRE THE REPAIR FACILITY TO OBTAIN YOUR ORAL OR WRITTEN AUTHORIZATION TO EXCEED THE WRITTEN PRICE ESTIMATE.

- 1. I request an estimate in writing before you begin repairs. Contact me if the price will exceed the estimate by more than ten percent.
2. Proceed with repairs but contact me if the price will exceed \$ \_\_\_\_\_.
3. I do not want a written estimate.

Signature: \_\_\_\_\_ Date: \_\_\_\_\_ Time: \_\_\_\_\_

Table with columns: Original Estimate (Parts & Labor), Estimate Additional Parts & Labor Costs, Additional Repairs Approved By / Telephone #, Name or ID # of Employee Obtaining Authorization, Date & Time.



**Final quick test log**

<b>Model series/Model designation</b>	240.179	<b>Workshop ID</b>	[Werkstattdata]
<b>VIN</b>	WDBVG79JX8A002414	<b>Steering</b>	LEFT
<b>Total distance driven</b>	103569 km	<b>Version</b>	7.7.2/03/2019 (2019-01-10)
<b>Battery voltage</b>	13.96 V		

<b>ETC - Electronic transmission control</b>				- ✓ -
<b>MB number</b> 0034464110	<b>HW version</b> 48.2006	<b>SW version</b> 50.2006	<b>Diagnosis version</b> 3/83	<b>Pin</b> 101
<b>FW number</b> 0034481410		<b>FW number (data)</b>	<b>FW number (boot SW)</b>	

<b>ESM - Electronic selector module</b>				- ✓ -
<b>MB number</b> 2205452632	<b>HW version</b> 11.2005	<b>SW version</b> 04.2003	<b>Diagnosis version</b> 0/11	<b>Pin</b> 9

<b>DTR - DISTRONIC</b>				- ✓ -
<b>MB number</b> 2095407845	<b>HW version</b> 07.11	<b>SW version</b> 07.36	<b>Diagnosis version</b> 0/2	<b>Pin</b> 101

<b>ME 2.7.2 - Motor electronics 2.7.2</b>				- ✓ -
<b>MB number</b> 0034460840	<b>HW version</b> 06.45	<b>SW version</b> 12.17	<b>Diagnosis version</b> 13/158	<b>Pin</b> 101
<b>FW number</b> 0094486840 2859021000		<b>FW number (data)</b> 2859030000	<b>FW number (boot SW)</b>	

03/2019 (2019-01-10)\AddOns: ([10840] ([11563] ([11569] ([11797] ([11848] ([11849] ([11850] ([11851] ([11852] ([11854] ([11855] ([11856] ([11857] ([11858] ([11860] ([11861] ([11863] ([11865] ([11867] ([11870] ([11873] ([11879] ([11881] ([11886] ([11889] ([11896] ([11899] ([11903] ([11906] ([11911] ([11913] ([11915] ([11918] ([11921] ([11923] ([11924] ([11926] ([11928] ([11933] ([11936] ([11940] ([11941] ([11944] ([11945] ([11948] ([11957] ([11958] ([11961] ([11963] ([11965] ([11970] ([11975] ([11977] ([11982] ([11984] ([11985] ([11987] ([11988] ([11992] ([11993] ([11997] ([11998] ([12000] ([12002] ([12004] ([12005] ([12006] ([12007] ([12011] ([12012] ([12013] ([12015] ([12017] ([12023] ([12027] ([12029] ([12030] ([12031] ([12033] ([12037] ([12039] ([12042] ([12044] ([12050] ([12053] ([12055] ([12060] ([12062] ([12064] ([12068] ([12072] ([12074] ([12079] ([12081] ([12082] ([12083] ([12086] ([12090] ([12093] ([12094] ([12098] ([12100] ([12102] ([12103] ([12106] ([12109] ([12112] ([12114] ([12115] ([12116] ([12119] ([12120] ([12123] ([12125] ([12126] ([12127] ([12132] ([12135] ([12137] ([12138] ([12142] ([12144] ([12146] ([12148] ([12149] ([12150] ([12153] ([12157] ([12158] ([12159] ([12162] ([12164] ([12165] ([12169] ([12171] ([12172] ([12173] ([12176] ([12177] ([12178] ([12180] ([12181] ([12182] ([12188] ([12189] ([12193] ([12195] ([12196] ([12198] ([12201] ([12203] ([12204] ([12206] ([12207] ([12213] ([12218] ([12219] ([12220] ([12223] ([12224] ([12227] ([12230] ([12231] ([12232] ([12234] ([12236] ([12238] ([12239] ([12240] ([12241] ([12242] ([12243] ([12251] ([12253] ([12254] ([12255] ([12257] ([12258] ([12259] ([12260] ([12261] ([12262] ([12263] ([12266] ([12269] ([12273] ([12274] ([12275] ([12277] ([12279] ([12281] ([12284] ([12285] ([12286] ([12290] ([12291] ([12294] ([12296] ([12300] ([12302] ([12304] ([12305] ([12312] ([12314] ([12315] ([12316] ([12317] ([12318] ([12328] ([12329] ([12333] ([12334] ([12336] ([12338] ([12346] ([12348] ([12350] ([12351] ([12358] ([12362] ([12364] ([12365] ([12368] ([12369] ([12370] ([12371] ([12372] ([12373] ([12377] ([12383] ([12386] ([12388] ([12390] ([12393] ([12397] ([12398] ([12403] ([12406] ([12409] ([12410] ([12413] ([12414] ([12415] ([12418] ([12419] ([12424] ([12425] ([12427] ([12429] ([12430] ([12432] ([12434] ([12435] ([12437] ([12438] ([12440] ([12441] ([12442] ([12447] ([12448] ([12449] ([12454] ([12455] ([12458] ([12460] ([12461] ([12462] ([12465] ([12467] ([12471] ([12473] ([12476] ([12478] ([12479] ([12481] ([12482] ([12489] ([12491] ([12493] ([12497] ([12498] ([12503] ([12505] ([12508] ([12512] ([12514] ([12517] ([12519] ([12523] ([12528] ([12532] ([12534] ([12536] ([12537] ([12538] ([12540] ([12543] ([12546] ([12551] ([12552] ([12554] ([12556] ([12559] ([12562] ([12566] ([12568] ([12569] ([12575] ([12582] ([12585] ([12589] ([12593] ([12594] ([12600] ([12602] ([12605] ([12606] ([12612] ([12614] ([12616] ([12620] ([12624] ([12625] ([12628] ([12635] ([12639] ([12640] ([12641] ([12644] ([12647] ([12655] ([12660] ([12662] ([12668] ([12672] ([12676] ([12677] ([12683] ([12684] ([12688] ([12691] ([12692] ([12695] ([12699] ([12709] ([12710] ([12717] ([12719] ([12721] ([12725] ([12727] ([12733]

<b>FSCU_A - Fuel pump</b>				- ✓ -
<b>MB number</b> 0365455332	<b>HW version</b> 06.23	<b>SW version</b> 06.22	<b>Diagnosis version</b> 1/1	<b>Pin</b> 101
<b>FW number</b> 0004420571		<b>FW number (data)</b>	<b>FW number (boot SW)</b>	

<b>SBC - Left Sensotronic Brake Control</b>				- ✓ -
<b>MB number</b> 2404300707	<b>HW version</b> 36.2005	<b>SW version</b> 44.2003	<b>Diagnosis version</b> 0/5	<b>Pin</b> 9

<b>SBC - Right Sensotronic Brake Control</b>				- ✓ -
<b>MB number</b> 2404300707	<b>HW version</b> 36.2005	<b>SW version</b> 44.2003	<b>Diagnosis version</b> 0/5	<b>Pin</b> 13

<b>ESP - Electronic stability program</b>				- ✓ -
<b>MB number</b> 0365452232	<b>HW version</b> 11.2005	<b>SW version</b> 11.2005	<b>Diagnosis version</b> 0/1	<b>Pin</b> 9

<b>AIRmatic</b>				- ✓ -
<b>MB number</b> 0375455732	<b>HW version</b> 26.2004	<b>SW version</b> 26.2007	<b>Diagnosis version</b> 3/11	<b>Pin</b> 101

<b>TPC - Tire pressure monitor</b>				- ✓ -
<b>MB number</b> 2405402945	<b>HW version</b> 17.2006	<b>SW version</b> 35.2006	<b>Diagnosis version</b> 0/13	<b>Pin</b> 101

<b>AB - Airbag</b>				- ✓ -
<b>MB number</b> 0038207526	<b>HW version</b> 06.20	<b>SW version</b> 06.40	<b>Diagnosis version</b> 0/12	<b>Pin</b> 101
<b>FW number</b>		<b>FW number (data)</b> 2404470142	<b>FW number (boot SW)</b>	

<b>WSS - Weight sensing system</b>				- ✓ -
<b>MB number</b> 2408201085	<b>HW version</b> 05.52	<b>SW version</b> 06.31	<b>Diagnosis version</b> 1/0	<b>Pin</b> 101

<b>System diagnosis (only interior CAN fault)</b>				- ✓ -
<b>MB number</b> 2405402545	<b>HW version</b> 10.2006	<b>SW version</b> 48.2005	<b>Diagnosis version</b> 1/4	<b>Pin</b> 101

<b>BNS - Vehicle power supply control module</b>				- ✓ -
<b>MB number</b> 2405400545	<b>HW version</b> 13.2005	<b>SW version</b> 21.2003	<b>Diagnosis version</b> 0/8	<b>Pin</b> 101

<b>EZS - Electronic ignition switch</b>				- ✓ -
---	--	--	--	-------

<b>MB number</b> 2405450708	<b>HW version</b> 37.2005	<b>SW version</b> 29.2006	<b>Diagnosis version</b> 2/5	<b>Pin</b> 101
<b>CGW - Central gateway</b>				- ✓ -
<b>MB number</b> 2405402545	<b>HW version</b> 10.2006	<b>SW version</b> 48.2005	<b>Diagnosis version</b> 2/2	<b>Pin</b> 101
<b>FW number</b> 2404480027 2404420127	<b>FW number (data)</b> 2404470251		<b>FW number (boot SW)</b>	
<b>Dr-side SAM - Driver signal acquisition and actuation module</b>				- ✓ -
<b>MB number</b> 2405452501	<b>HW version</b> 10.2003	<b>SW version</b> 05.2004	<b>Diagnosis version</b> 0/2	<b>Pin</b> 101
<b>Pass-side SAM - Passenger-side signal acquisition and actuation module</b>				- ✓ -
<b>MB number</b> 2405451601	<b>HW version</b> 10.2003	<b>SW version</b> 13.2003	<b>Diagnosis version</b> 0/1	<b>Pin</b> 101
<b>Rear SAM 1 - Rear signal acquisition and actuation module 1</b>				- ✓ -
<b>MB number</b> 2405450401	<b>HW version</b> 13.2006	<b>SW version</b> 25.2003	<b>Diagnosis version</b> 0/5	<b>Pin</b> 101
<b>Rear SAM 2 - Rear signal acquisition and actuation module 2</b>				- ✓ -
<b>MB number</b> 2405451501	<b>HW version</b> 13.2006	<b>SW version</b> 46.2003	<b>Diagnosis version</b> 0/6	<b>Pin</b> 101
<b>MSS - Special vehicle multifunction control module</b>				- ✓ -
<b>MB number</b> 2408202285	<b>HW version</b> 23.2003	<b>SW version</b> 18.2006	<b>Diagnosis version</b> 2/1	<b>Pin</b> 101
<b>VBF (Front control panel) - Front control panel</b>				- ✓ -
<b>MB number</b> 2408215751	<b>HW version</b> 25.2002	<b>SW version</b> 20.2004	<b>Diagnosis version</b> 128/8	<b>Pin</b> 101
<b>HBF (Rear control panel) - Rear control field</b>				- ✓ -
<b>MB number</b> 2408706310	<b>HW version</b> 25.2002	<b>SW version</b> 50.2004	<b>Diagnosis version</b> 1/0	<b>Pin</b> 101
<b>OCP - Overhead control panel</b>				- ✓ -
<b>MB number</b> 2408200223	<b>HW version</b> 19.2003	<b>SW version</b> 03.2004	<b>Diagnosis version</b> 0/1	<b>Pin</b> 101
<b>CRN - Center roof node</b>				- ✓ -
<b>MB number</b> 2408201885	<b>HW version</b> 19.2004	<b>SW version</b> 03.2005	<b>Diagnosis version</b> 0/0	<b>Pin</b> 101

<b>DCM-RR - Door control module rear right</b>				- ✓ -
<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
2408200685	45.2002	20.2004	0/3	101
<b>PWC - Partition wall control module</b>				- ✓ -
<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
2408200285	45.2002	20.2004	0/3	101
<b>LDCA - Electric left door closing assist</b>				- ✓ -
<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
2408206526	49.2002	43.2003	0/2	101
<b>RDCA - Electric right door closing assist</b>				- ✓ -
<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
2408206626	49.2002	43.2003	0/2	101
<b>TLC - Trunk lid control</b>				- ✓ -
<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
2118703026	37.2004	27.2004	0/2	101
<b>OSB-FL - Multicontour backrest front left</b>				- ✓ -
<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
2408000078	14.1999	48.2001	128/0	101
<b>OSB-FR - Multicontour backrest front right</b>				- ✓ -
<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
2408000078	14.1999	48.2001	128/0	101
<b>MKL-HL - Rear left multicontour backrest</b>				- ✓ -
<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
2408000078	14.1999	48.2001	128/0	101
<b>MKL-HR - Rear right multicontour backrest</b>				- ✓ -
<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
2408000078	14.1999	48.2001	128/0	101
<b>ICM - Instrument cluster</b>				- ✓ -
<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
2405402511	24.2005	06.2007	9/5	101
<b>SCM [MRM] - Steering column module</b>				- ✓ -
<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
0305459632	03.2002	19.2001	0/0	101

<b>PSE - Pneumatic system equipment</b>				- ✓ -
<b>MB number</b> 2408000148	<b>HW version</b> 05.2002	<b>SW version</b> 34.2004	<b>Diagnosis version</b> 128/3	<b>Pin</b> 101

<b>HRA - Automatic headlamp range adjustment and headlamp control</b>				- ✓ -
<b>MB number</b> 2198202526	<b>HW version</b> 23.2003	<b>SW version</b> 34.2006	<b>Diagnosis version</b> 130/1	<b>Pin</b> 101

<b>ESA-FL - Electric seat adjustment front left</b>				- ✓ -
<b>MB number</b> 2408202326	<b>HW version</b> 15.2002	<b>SW version</b> 44.2003	<b>Diagnosis version</b> 0/3	<b>Pin</b> 101

<b>ESA-FR - Electric seat adjustment front right</b>				- ✓ -
<b>MB number</b> 2408202426	<b>HW version</b> 15.2002	<b>SW version</b> 44.2003	<b>Diagnosis version</b> 0/3	<b>Pin</b> 101

<b>ESA-LR - Left rear electrical seat adjustment</b>				- ✓ -
<b>MB number</b> 2408203185	<b>HW version</b> 15.2002	<b>SW version</b> 51.2006	<b>Diagnosis version</b> 0/2	<b>Pin</b> 101

<b>ESA-RR - Right rear electrical seat adjustment</b>				- ✓ -
<b>MB number</b> 2408203285	<b>HW version</b> 15.2002	<b>SW version</b> 51.2006	<b>Diagnosis version</b> 0/2	<b>Pin</b> 101

<b>PTS - Parktronic system</b>				- ✓ -
<b>MB number</b> 2405450432	<b>HW version</b> 04.2004	<b>SW version</b> 03.2004	<b>Diagnosis version</b> 6/3	<b>Pin</b> 101

<b>DCM-FL - Door control module front left</b>				- ✓ -
<b>MB number</b> 2408200385	<b>HW version</b> 45.2002	<b>SW version</b> 20.2004	<b>Diagnosis version</b> 0/3	<b>Pin</b> 101

<b>DCM-FR - Door control module front right</b>				- F -
<b>MB number</b> 2408200485	<b>HW version</b> 45.2002	<b>SW version</b> 20.2004	<b>Diagnosis version</b> 0/3	<b>Pin</b> 101

Code	Text	Status
9208	The signal line of component M21/2r2 (Mirror adjustment up/down potentiometer) has Short circuit or open circuit or the component is defective.	Current and stored
9209	The signal line of component M21/2r3 (Mirror adjustment in/out potentiometer) has Short circuit or open circuit or the component is defective.	Current and stored

<b>DCM-RL - Door control module rear left</b>				- ✓ -
<b>MB number</b> 2408200585	<b>HW version</b> 45.2002	<b>SW version</b> 20.2004	<b>Diagnosis version</b> 0/3	<b>Pin</b> 101

<b>AGW - Audio gateway (MOST network management, diagnosis gateway, radio tuner)</b>					- ✓ -
<b>MB number</b> 2118271062	<b>HW version</b> 29.2003	<b>SW version</b> 51.2005	<b>Diagnosis version</b> 6/65	<b>Pin</b> 101	
<b>Serial number</b> BE603281176521					

<b>COMAND ( The MB object number is invalid. Replacement part ordering via EPC )</b>					- ✓ -
<b>MB number</b> -----	<b>HW version</b> 43.2007	<b>SW version</b> 03.2007	<b>Diagnosis version</b> 4/69	<b>Pin</b> 101	
<b>Serial number</b> BE702681011537					

<b>NAVI - Navigation</b>					- ✓ -
<b>MB number</b> 2118705785	<b>HW version</b> 43.2007	<b>SW version</b> 45.2006	<b>Diagnosis version</b> 1/194	<b>Pin</b> 101	
<b>Serial number</b> BE704285691370					

<b>VCS - Voice control system</b>					- ✓ -
<b>MB number</b> 2038208285	<b>HW version</b> 05.2007	<b>SW version</b> 50.2005	<b>Diagnosis version</b> 1/66	<b>Pin</b> 101	

<b>TV - TV tuner</b>					- ✓ -
<b>MB number</b> 2118272762	<b>HW version</b> 19.2007	<b>SW version</b> 11.2007	<b>Diagnosis version</b> 10/193	<b>Pin</b> 101	
<b>Serial number</b> DL000081010034					

<b>SOUND - Bose sound system</b>					- ✓ -
<b>MB number</b> 2408270062	<b>HW version</b> 18.2003	<b>SW version</b> 17.2006	<b>Diagnosis version</b> 1/195	<b>Pin</b> 101	
<b>Serial number</b> BS000136000062					

<b>Control unit TELE AID</b>					- ✓ -
<b>MB number</b> 2044460159	<b>HW version</b> 07.13	<b>SW version</b> 07.28	<b>Diagnosis version</b> 3/73	<b>Pin</b> 101	
<b>Serial number</b> PE10109522	<b>FW number</b> 2044420259	<b>FW number (data)</b> 2044423660 2044423560	<b>FW number (boot SW)</b>		

<b>TELE AID - Telematic services MB Info , Roadside assistance ( USA, Canada ), Tele diagnosis ( ECE )</b>					- ✓ -
<b>MB number</b> 2034470259	<b>HW version</b> 07.13	<b>SW version</b> 07.28	<b>Diagnosis version</b> 2/64	<b>Pin</b> 101	

<b>TELE AID - Telematic service Stolen vehicle tracking</b>					- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin	
2034470159	07.13	07.28	2/64	101	
<b>TELE AID - Telematic services Remote door unlocking , Remote door locking</b>					- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin	
2214470059	07.13	07.28	2/65	101	
<b>TELE AID - Telematic service Emergency call</b>					- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin	
2034470059	07.13	07.28	2/64	101	
<b>SDAR - Satellite radio</b>					- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin	
2118706790	42.2006	33.2007	2/64	101	
<b>CTEL - Mobile phone adapter with universal interface</b>					- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin	
2408200985	41.2004	38.2004	5/64	101	
Serial number DY60000533					
<b>AVC - Audio video controller</b>					- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin	
2408201385	03.2004	46.2004	3/25	12	
<b>TV - TV tuner (rear)</b>					- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin	
2408270162	03.2006	08.2006	10/0	12	
Serial number DL					
<b>CDC - CD changer ( REAR )</b>					- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin	
2408204889	13.2002	22.2002	2/2	12	
<b>KTL - Left headphone transmitter</b>					- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin	
2408200785	11.2006	20.2006	2/7	12	
<b>KTR - Right headphone transmitter</b>					- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin	
2408200785	11.2006	20.2006	2/7	12	
<b>AAC - Automatic air conditioning</b>					- ✓ -

<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
2408300185	07.2003	36.2003	1/4	101
<b>HSW - Heated steering wheel</b>				- ✓ -
<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
0295452932	32.2003	47.2001	0/18	101
<b>REAR AC - Rear air conditioning</b>				- ✓ -
<b>MB number</b>	<b>HW version</b>	<b>SW version</b>	<b>Diagnosis version</b>	<b>Pin</b>
2408300285	07.2003	36.2003	2/4	101