



**FINANCING
AVAILABLE**

AVOID ATTIC RAIN!

In Saskatchewan's frequent cold spells, ice buildup is common, leading to attic moisture when temperatures rise. This melting frost can cause water to run down walls, soak plywood roofs, and collect around fixtures, leading to ceiling stains, roof leaks, and drips from pot lights, attic hatches, and bathroom fans.

Get a complete attic upgraded

The removal of old insulation, air sealed, ventilated properly to eliminate moisture and mold growth in the attics.

**GREENER
SOLUTIONS**

Request a Quote:
306.540.6557

Upgrade or add blown in insulation for your attic. It will protect your home from the outside environment and keep you and your family comfortable inside.

SIGNS OF ATTIC RAIN

- Water stains on ceiling and/or around light fixtures
- Condensation that is visible on attic surfaces
- Wet insulation
- Water drips from light fixtures
- Mold or mildew growth
- Musty odors in the attic

Get a complete attic upgraded

The removal of old insulation, air sealed, ventilated properly to eliminate moisture and mold growth in the attics.

GREENER
SOLUTIONS

Request a Quote:
306.540.6557

Greener Solutions can be in and out ensuring timelines are met, always. Our product is maintenance free and will continue to benefit your family for years to come.



**FINANCING
AVAILABLE**

